



WELLINGTON E. WEBB
Mayor

CITY AND COUNTY OF DENVER

DEPARTMENT OF ENVIRONMENTAL HEALTH
CHRIS VEASEY, Ph.D., MANAGER

ENVIRONMENTAL SERVICES DIVISION
DIANA SHANNON, DIVISION DIRECTOR
201 WEST COLFAX AVENUE
DEPARTMENT 1009
DENVER, COLORADO 80202
PHONE: (720) 865-5430
FAX: (720) 865-5534
www.denvergov.org



December 30, 2002

PUBLIC
DOCUMENT

Ms. Bonita Lavelle, Remedial Project Manager
EPA Region 8 (8EPR-SR)
U.S. Environmental Protection Agency
999 18th Street, Suite 300
Denver, CO 80202-2466

Re: Supplemental Information Pursuant to §104 of CERCLA for Vasquez Boulevard/I-70
(VBI70) Superfund Site – Denver, CO

Dear Bonnie:

The following information is intended to supplement the City and County of Denver's (Denver) January 26, 2000 response to the First Request for Information for the above referenced site.

Samples were collected in July 2002 from two soil stockpiles located at Operable Unit 2 that were no longer needed by the Denver Coliseum. The material was tested for Arsenic and Lead using EPA Method 6020. In addition, Toxicity Characteristic Leaching Procedure (TCLP) for metals analysis was run on one composite sample to determine proper management and disposal. The results showed that the concentrations of arsenic and lead were non-hazardous and are included in the data package attached to this letter.

Do not hesitate to contact me at 720-865-5426 if you should have any questions.

Sincerely,

A handwritten signature in cursive script that reads "Cindy Bosco".

Cindy Bosco, CHMM
Environmental Scientist

Encl: "Soil Stockpile Removal Between Denver Coliseum West Parking Lot and Globeville Landing Park, Sampling Results and Removal Summary"

cc: Diana Shannon, Dennis Bollmann, Shaun Sullivan
Barbara O'Grady, CDPHE (w/ encl.)
Bob Litle, Asarco (w/ encl.)